

Maintenance Tracking Report 1

December 30, 2021

Schweizer 300C

S/N S1708

Registration C-FWPB

Total Time: 2478.6

Item No.	Component	P/N	S/N	Service Life		Component Time Since NEW/OH	Component TSOH at Install	Installed at Airframe Hours	Component Time Since Install	Remove at Airframe Time	Total Time Remaining
5.00	Engine	HIO-360-D1A	L-26602-51A	1,500	OH	992.5	0.0	1,486.1	992.5	2,986.1	507.5
10.00	M/R Blade	269A1185-001	S1152	5,500	RT	2,476.5	1.7	3.8	2,474.8	5,502.1	3,023.5
13.00											
20.00	M/R Blade	269A1185-001	S1168	5,500	RT	2,476.5	1.7	3.8	2,474.8	5,502.1	3,023.5
30.00	M/R Blade	269A1185-001	S1140	5,500	RT	2,476.5	1.7	3.8	2,474.8	5,502.1	3,023.5
85.00	Pitch Housing Assy.	269A1221-005	S0801		OC	2,480.3	1.7	0.0	2,478.6	N/A	N/A
90.00	Pitch Housing Assy.	269A1221-005	S0803		OC	2,480.3	1.7	0.0	2,478.6	N/A	N/A
95.00	Pitch Housing Assy.	269A1221-005	S0827		OC	2,478.6	0.0	0.0	2,478.6	N/A	N/A
100.00	Main Rotor Pitch Shaft	269A1240-007	S4201	3,600	RT	2,480.3	1.7	0.0	2,478.6	3,598.3	1,119.7
105.00	Main Rotor Pitch Shaft	269A1240-007	S4200	3,600	RT	2,480.3	1.7	0.0	2,478.6	3,598.3	1,119.7
107.00	Main Rotor Pitch Shaft	269A1240-007	S4211	3,600	RT	2,480.3	1.7	0.0	2,478.6	3,598.3	1,119.7
110.00	Main Rotor Damper	269A1290-003	10539	6,000	RT	0.0	0.0	2,261.3	217.3	8,261.3	6,000.0
115.00	Main Rotor Damper	269A1290-003	10497	6,000	RT	0.0	0.0	2,261.3	217.3	8,261.3	6,000.0
120.00	Main Rotor Damper	269A1290-003	10496	6,000	RT	0.0	0.0	2,261.3	217.3	8,261.3	6,000.0
130.00	Main Rotor Mast	269A2010-006	S0610	13,590	RT	2,478.6	0.0	0.0	2,478.6	13,590.0	11,111.4
140.00	Main Rotor Thrust Bearing	269A5050-063	3144	3,000	RT	2,478.6	0.0	0.0	2,478.6	3,000.0	521.4
145.00	Tail Boom Support Strut	269A2015-011	S1357	10,700	RT	2,478.6	0.0	0.0	2,478.6	10,700.0	8,221.4
150.00	Tail Boom Support Strut	269A2015-011	S1530	10,700	RT	905.4	0.0	1,573.2	905.4	12,273.2	9,794.6
155.00	Tailboom	296A2320-17	S0724	4,200	RT	440.3	0.0	2,038.3	440.3	6,238.3	3,759.7
160.00	Vertical Stabilizer	269A2419-003	S2249	20,540	RT	2,478.6	0.0	0.0	2,478.6	20,540.0	18,061.4
165.00	Horizontal Stabilizer	269A2516-009	S5656	2,500	RT	0.0	0.0	2,478.6	0.0	4,978.6	2,500.0
166.00	Lower Bearing	269A5050-85	2350	1,800	RT	574.8	0.0	1,903.8	574.8	3,703.8	1,225.2
167.00	Lower Bearing	269A5050-85	2324	1,800	RT	574.8	0.0	1,903.8	574.8	3,703.8	1,225.2

Maintenance Tracking Report 2

December 30, 2021

Schweizer 300C

S/N S1708

Registration C-FWPB

Total Time: 2,478.6

Item No.	Component	P/N	S/N	Service Life		Component Time Since NEW/OH	Component TSOH at Install	Installed at Airframe Hours	Component Time Since Install	Remove at Airframe Time	Total Time Remaining
170.00	M/R Transmission	269A5175-023	S0551	3,000	OH	2,474.8	0.0	3.8	2,474.8	3,003.8	525.2
175.00	M/R Trans. Pinion	269A5103-051	S3083AGC	6,000	RT	2,474.8	0.0	3.8	2,474.8	6,003.8	3,525.2
180.00	Carrier	269A5193-1	S373	6,000	RT	2,474.8	0.0	3.8	2,474.8	6,003.8	3,525.2
185.00	Bearing	269A5051-20	4454	3,000	RT	2,474.8	0.0	3.8	2,474.8	3,003.8	525.2
190.00	M/R Hub Assy	269A5325-001	S0669	8,000	RT	574.8	0.0	1,903.8	574.8	9,903.8	7,425.2
195.00	M/R Drive Shaft	269A5326-005	SZ0196	3,200	RT	574.8	0.0	1,903.8	574.8	5,103.8	2,625.2
205.00	Lwr. Pulley Couplg. Shaft	269A5559-003	S2130	6,000	RT	217.3	0.0	2,261.3	217.3	8,261.3	5,782.7
210.00	T/R Transmission	269A5600-703	S0018	3,000	OH	2,478.6	0.0	0.0	2,478.6	3,000.0	521.4
215.00	T/R Input Shaft	269A5626-005	S375ACR	8,600	RT	2,478.6	0.0	0.0	2,478.6	8,600.0	6,121.4
220.00	T/R Blade	269A6035-023	S1996	9,000	RT	2,478.6	0.0	0.0	2,478.6	9,000.0	6,521.4
225.00	T/R Blade	269A6035-023	S1987	9,000	RT	2,478.6	0.0	0.0	2,478.6	9,000.0	6,521.4
230.00	T/R Retention Strap	269A6065-507	S1350	5,100	RT	2,478.6	0.0	0.0	2,478.6	5,100.0	2,621.4
235.00	T/R Drive Shaft	269A6040-007	S1753	6,000	RT	2,478.6	0.0	0.0	2,478.6	6,000.0	3,521.4
236.00	Upper Bearings	269A5050-096		3,000	RT	574.8	0.0	1,903.8	574.8	4,903.8	2,425.2
	Magneto	4345	19030466	500	IN	0.0	0.0	2,478.6	0.0	2,978.6	500.0
				1,500	OH	0.0	0.0	2,478.6	0.0	3,978.6	1,500.0
	Magneto	4345	19030463	500	IN	0.0	0.0	2,478.6	0.0	2,978.6	500.0
				1,500	OH	0.0	0.0	2,478.6	0.0	3,978.6	1,500.0
	Blower Motor	ES61034-1	N/A			127.2	0.0	2,351.4	127.2		
	Starter (new)	149-24HT	F4C-461501			168.8	0.0	2,309.8	168.8		
	Alternator (overhauled)	ALU-8421LS	H-Q031280			127.2	0.0	2,351.4	127.2		
	Lead Acid Battery	RG24-11M	41071587		IN	0.0	0.0	2,478.6	0.0		
	Fuel Boost Pump	269A4090-001	58793			127.2	0.0	2,351.4	127.2		
	Filter	BA-2		200	RT	29.6	0.0	2,449.0	29.6	2,649.0	170.4
	Shaft-Lower	269A5498-005	N/A			217.3	0.0	2,261.3	217.3		

Maintenance Tracking Report 3

December 30, 2021

Schweizer 300C

S/N S1708

Registration C-FWPB

Total Time: 2,478.6

Item No.	Component	P/N	S/N	Service Life		Component Time Since NEW/OH	Component TSOH at Install	Installed at Airframe Hours	Component Time Since Install	Remove at Airframe Time	Total Time Remaining
	25 Hour Inspection			25	IN	0.0	0.0	2478.6	0.0	2,503.6	25.0
	50 Hour Inspection			50	IN	0.0	0.0	2478.6	0.0	2,528.6	50.0
510.00	100 Hour Inspection			100	IN	0.0	0.0	2,478.6	0.0	2,578.6	100.0
520.00	200 Hour Inspection			200	IN	29.6	0.0	2,449.0	29.6	2,649.0	170.4
530.00	300 Hour Inspection			300	IN	172.4	0.0	2,306.2	172.4	2,606.2	127.6
540.00	400 Hour Inspection			400	IN	323.6	0.0	2,155.0	323.6	2,555.0	76.4
550.00	600 Hour Inspection			600	IN	172.4	0.0	2,306.2	172.4	2,906.2	427.6
560.00	1200 Hour Inspection			1,200	IN	716.4	0.0	1,762.2	716.4	2,962.2	483.6
	Lower Shaft NDT	269A5559-003	S2130	150	IN	92.6	0.0	2,386.0	92.6	2,536.0	57.4
511.00	Repetitive AD	AD 78-02-02	N-121.1 SIN	100	IN	29.6	0.0	2,449.0	29.6	2,549.0	70.4
512.00	Repetitive AD	AD 82-15-03	N-182 SIN	100	IN	29.6	0.0	2,449.0	29.6	2,549.0	70.4
513.00	Repetitive AD	AD 2002-26-01	342D	100	IN	29.6	0.0	2,449.0	29.6	2,549.0	70.4
531.00	Repetitive AD	AD 94-12-06		300	IN	176.1	0.0	2,302.5	176.1	2,602.5	123.9
Item No.	Component	P/N	S/N	Service Life		Date Installed	Date to be Removed				
485.00	ELT Battery	ME-406HM		60 mo.		Dec-18	Dec-23				
485.01	ELT Re-certify	ME-406HM		12 mo.		Dec-20	Dec-21				
490.00	Transponder Recertify	KT-76A	99727	24 mo.		Feb-20	Feb-21				
500.00	Compass Swing			12 mo.		Feb-18	Feb-19				
505.00	M/R Swash Plate Re-grease			24 mo.		Mar-20	Mar-21				
510.00	T/R Swash Plate Re-grease			24 mo.		Mar-20	Mar-21				
515.00	Fire Ext. Recertify			12 mo.		Mar-20	Mar-21				
520.00	First Aid Kit			12 mo.		Mar-20	Mar-21				
600.00	Annual Inspection			12 mo.		Mar-20	Mar-21				